

April 17, 1998

GFK-1397E

IMPORTANT PRODUCT INFORMATION

READ THIS INFORMATION FIRST

Product: CIMPLICITY® Control, Version 2.1

IC641CTL970F	Control 90-70 Programmer w/CD Documentation
IC641CTL971F	Control 90-70 Programmer w/paper Documentation
IC641CTL170F	Control 90-70 Programmer Logicmaster 90 upgrade
IC641CTL171F	Control 90-70 Programmer Subscription upgrade
IC641CTL930D	Control 90-30 Programmer w/CD Documentation
IC641CTL931D	Control 90-30 Programmer w/paper Documentation
IC641CTL130D	Control 90-30 Programmer Logicmaster 90 upgrade
IC641CTL990D	Professional Developer Package 90-70, 90-30, SFC
IC641CTL991F	Distributor Demo 10 pack
IC641CTL993F	OEM Evaluation Kit – 30 day license
IC641CTL972D	Upgrade to add 90-70 target
IC641CTL932D	Upgrade to add 90-30 high end target
IC641CTL950A	SFC language editor
IC641CTL937B	Programmer Toolkit

CIMPLICITY Control Version 2.1 is an IEC 1131-3 based programming product for use with GE Fanuc Series 90™-30 (Models 350, 351, 352 and 360) and Series 90™-70 controllers. CIMPLICITY Control runs under Windows® 95 and Windows NT® 4.0. Built on the latest Microsoft technology, CIMPLICITY Control is designed to adhere to industry standards including Microsoft Foundation Classes (MFC) 4.0, ODBC, and OLE 2.0, making CIMPLICITY Control easy to use and integrate with other applications.

This release provides support for Genius® Redundancy, CPU Redundancy over Genius, Series 90-30 Profibus configuration, and modem dialing and communications for SNP. This release also supports Ethernet routing, SNTP configuration, and enhancements to EGD (Ethernet Global Data).

Operational Notes

1. System Requirements

CIMPLICITY Control is compatible with Windows 95 and Windows NT 4.0. The following versions of Windows are recommended:

Windows 95 Service Pack 1 (4.00.950A) or OEM Service Release 2 (4.00.950B)
 Windows NT Service Pack 3 or later.

Your system must meet the following minimum requirements* to successfully install and run CIMPLICITY Control for Windows 95 and Windows NT. If free hard drive space requirements are not maintained, CIMPLICITY Control and the underlying operating system may not operate correctly.

System Features	For Windows 95		For Windows NT	
	Minimum	Recommended	Minimum	Recommended
CPU	Pentium/60	Pentium/133	Pentium/75	Pentium/133
RAM	16 MB	32 MB	24 MB	48 MB
Free Hard Disk Space	75 MB	75 MB	100 MB	100 MB
CD-ROM Drive	Yes	Yes	Yes	Yes

CIMPLICITY Control Version 2.1 is not compatible with Windows 98 preview or Windows 98 Beta.

If the Internet Browser desktop that comes with Internet Explorer 4.0 from Microsoft is installed and made the default desktop, CIMPLICITY Control users may experience display problems.

2. Installation

Installing CIMPLICITY Control Version 2.1:

CIMPLICITY Control is distributed on CD-ROM. To install CIMPLICITY Control, insert the CD-ROM into the CD-ROM drive. To view the contents of the CD-ROM, click the drive letter configured for your CD-ROM, (typically D:\) from Explorer or File Manager. Double-click the icon beside setup.exe.

Review the following notes for technical information about CIMPLICITY Control installation:

- If you are upgrading your version of CIMPLICITY Control, run the Uninstall utility provided in the CIMPLICITY Control program group to uninstall the existing version. During the uninstall, you will be asked if you wish to retain the current license. If you are upgrading from CIMPLICITY Control Version 1.0, 1.1, or a *beta* version of 2.0, choose "No". If you are upgrading from CIMPLICITY Control Version 2.0 or higher, choose "Yes" to retain your current license. If you choose "No", you will need to reregister your software. The Option Setup item in the Program Group lists the phone numbers to call to obtain a new license.
- If you are installing on a computer that has dual boot into Windows 95 or Windows NT, you should un-install and then install on one operating system, then boot into the other operating system, repeating the procedure.

* These requirements are for CIMPLICITY Control running as a single application. Memory requirements to run applications simultaneously are additive. Acceptable performance is subjective and can be enhanced by employing more RAM memory and faster processors as they become available.

- In addition to program files, CIMPLICITY Control installs Microsoft support files in the Windows system directory. If these files exist, they will be replaced only if CIMPLICITY Control requires a later version than the one currently installed.
- If you attempt the installation when other Windows applications are open, you may see messages saying the install has attempted to update a read-only file. Answer NO to the prompt asking whether to update the file. You should exit the Install program (ALT+F3), close all Windows applications and restart the CIMPLICITY Control installation program. If the message persists, reboot your machine and repeat the process.
- CIMPLICITY Control uses the GEF_CFG.INI file that is placed in the Windows root directory to record communications device configurations. This file is also used by CIMPLICITY HMI and Motion, as well as other applications developed with the Host Communications Toolkit for communicating with GE Fanuc PLCs. If the file already exists, a prompt will display asking if the file should be overwritten. To keep your existing file, select NO. If you overwrite the file, you may lose configuration information used by software programs that access GE Fanuc PLCs. The new default file will be placed in GEF_CFG.SMP. This file has new settings for the Serial ports that should be edited into the existing GEF_CFG.INI file. This can be done using either a text editor or the Communications Configuration Utility application that is provided as part of CIMPLICITY Control.
- If CIMPLICITY Control and CIMPLICITY PC Control are installed on the same machine, un-installing CIMPLICITY PC Control will cause CIMPLICITY Control to lose the ability to communicate with PLCs. Do not un-install CIMPLICITY PC Control unless you plan to remove both packages from the machine.

3. Demo Mode

If you do not register your version of CIMPLICITY Control or do not have a licensed copy of CIMPLICITY Control, the product will operate in demo mode. The demo mode allows you to use all features of the product but with limited reference table sizes. You also cannot view an Equipment Folder created with a licensed product.

Equipment Folders

- Only 90-30 or 90-70 Demo Equipment Folders can be created or opened in demo mode. They will have a file extension name of .d3x .e7d, respectively.
- Real 90-30 or 90-70 Equipment Folders (those created with a licensed copy) cannot be accessed when operating in demo mode.
- Demo Equipment Folders cannot be converted to or saved as real 90-30 or 90-70 Equipment Folders. Real 90-30 or 90-70 Equipment Folders cannot be converted to or saved as Demo 90-30 or 90-70 Equipment Folders.

Load from, Store to the PLC

- You cannot load any programs from the PLC to CIMPLICITY Control when operating in demo mode.
- Demo Equipment Folders can be stored to the PLC.

Programming Restrictions

- CIMPLICITY Control demo equipment folders use the following reference table sizes:

%I1-16	%Q1-16	%M1-16	%R1-48	%AI1-4	%AQ1-4
%S1-128 (90-70)	%S1-32 (90-30)	%SA1-128 (90-70)	%SA1-32 (90-30)		
%SB1-128 (90-70)	%SB1-32 (90-30)	%SC1-128 (90-70)	%SC1-32 (90-30)		
%P1-10 (90-70 only)	%L1-10 (90-70 only)				
%G1-16	%GA none	%GB none	%GC none	%GD none	%GE none
%T none					

Note

When viewing references online in demo mode, you will see only the ranges available in demo mode.

- CIMPLICITY Control Demo Equipment Folders use the following locations for auto-variable locate:

Config: Discrete %M1-4 Non-Discrete %R1-5

Program: Discrete %M9-12 Non-Discrete %P1-5 (90-70). %R11-15 (90-30)

Local: Discrete %M13-16 Non-Discrete %L1-5 (90-70), %R16-20 (90-30)

Product Compatibility

CIMPLICITY Control Version 2.1 provides programming and hardware configuration support for the Series 90-30 Model 350, 351, 352 (Version 6.61 or higher) and 360 and Series 90-70 CPUs. With restrictions described later in this section, this release provides the same feature set as Logicmaster 90-70, Version 7.02, and Logicmaster 90-30, Version 8.01, with the following exceptions: Single word changes on the 90-70, mixed reference tables, and Remote Rack Configuration (BEM733). Additional features beyond Logicmaster 90 for SFC programs include support for up to eight actions per step and the ability to program SFC in 90-30 subroutines.

1. Hardware Compatibility

This version of CIMPLICITY Control supports the following Series 90-30 modules:

Series 90-30 CPUs	IC693CPU350, IC693CPU350, IC69CPU352, IC693CPU360
Series 90-30 Discrete I/O	All modules supported
Series 90-30 Analog I/O	IC693ALG220, IC693ALG221, IC693ALG222, IC693ALG223, IC693ALG390, IC693ALG391, IC693ALG392, IC693ALG442
Communications	IC693CMM311 Communication Coprocessor IC693CMM321 Ethernet Interface IC693CMM301 Genius® Communications Module IC693CMM302 Enhanced Genius Communications Module
Motion	IC693APU300 High Speed Counter Module IC693APU305 90-30 I/O Processor Module IC693APU301 Motion Mate APM 1-Axis IC693APU302 Motion Mate APM 2-Axis IC693APU305 90-30 I/O Processor Module IC693MCM001 Digital Servo Interface Unit
Bus Controller	IC693BEM321 90-30 I/O Link Master IC693BEM331 90-30 Genius Bus Controller
Intelligent Option Modules	IC693ADC311 Alphanumeric Display Coprocessor IC693PCM300 Programmable Coprocessor 160KB IC693PCM301 Programmable Coprocessor 192KB IC693PCM311 Programmable Coprocessor 640KB

This version of CIMPLICITY Control supports the following Series 90-70 and Genius modules:

Series 90-70 CPUs*	90-70 Intelligent Option Modules
IC697CPU731	Communications Coprocessor Module
IC697CPU732	GENet MAP Carrierband (Single Slot)
IC697CPU771	GENet MAP Broadband
IC697CPU772	Ethernet Controller Type 1
IC697CPU781	Ethernet Controller Type 2
IC697CPU782	DLAN Interface Module
IC697CPU788	Bus Transmitter Module
IC697CPU789	Genius Bus Controller Module
IC697CPU790	Peer Communications Module
IC697CPM914	High Speed Counter Module
IC697CPM915	Alpha-numeric Display Module
IC697CPM924	Graphics Display Coprocessor Module
IC697CPM925	
IC697CGR935	

Series 90-70 I/O	All modules supported
Genius devices	All Phase B Genius I/O blocks are supported
Field Control I/O	Field Control I/O using the Genius BIU are configured as generic I/O on the Genius Bus

Genius Block Configuration Note (For Series 90-70)

If you have configured Genius blocks using CIMPLICITY Control Version 2 *beta* 3 or earlier, the resulting H/W Configuration will not be compatible with Version 2.1. (Configurations done using *beta* 4 and later versions are compatible.) You will need to either re-enter the configuration using Version 2 or store the H/W Configuration to a PLC with the previous *beta* version and load it into a folder using Version 2.

* Release 4 or later 90-70 CPU firmware

** Release 3 or later 90-70 GBC firmware required

2. Configuring Remote Racks with CIMPPLICITY Control, Version 2.1

Version 2.1 does not support remote rack configuration (IC697BEM733). However, remote racks can be configured for use over the Genius Bus using the following procedure:

- a) Configure the Genius Bus Controller
- b) Expand the Genius Bus
- c) Add a Generic I/O block at the System Bus Address of the remote 90-70 I/O rack.
- d) Configure the remote rack using Logicmaster 90-70.

3. Version 1.0 and 1.1 Folder Compatibility

Folders created with Version 1.0 or Version 1.1 are forward compatible with Version 2.1. A conversion process is automatically invoked whenever a Version 1.0 or 1.1 folder is opened. You will be prompted for a new directory in which to put the old version of the folder. Once converted to Version 2.0/2.1 format, the folder can no longer be opened with Version 1.0 or 1.1 of CIMPPLICITY Control.

Folders that were created using Version 1.0 and Version 1.1 may have blocks out of synchronization with the Neutral Form and binary representations, corrupted Comments, real-time updates in LD showing the wrong values, and Cross-References listing incorrect rungs. These problems were generally introduced when CIMPPLICITY Control abnormally terminated during an editing session. The following folder repair procedure can be used to clean-up corrupted Version 1.0 or 1.1 folders after the automatic conversion to Version 2.1 has been completed.

Folder Repair Procedure for old VERSION 1.0 or 1.1 Folders

You can do this procedure efficiently by running two instances of the Workbench on the same machine. One instance is used to copy from the old folder, the other to paste to the new folder.

1. Export all variables from the old folder to an .snf file. Click on Variable Declaration Table. Select All Visible Scopes, ALL Refs, ALL Types. Select All from the Edit Menu. Select Variables->Export... Export variable to snf file. Edit the snf file to remove all variables that have “_” in them. These are internal variables that should not be imported.
2. Create a new folder.
3. Set up CPU Model and CPU Reference Limits in the new folder’s Hardware Configuration (%AI, %AQ, and %R size).
4. Set up Auto Variable Locate values to match program. Edit Resource, Program -> Auto Variable Locate...
5. Import Variables from the .snf file to the new folder.
6. Create all empty Blocks in the new folder using the New Block... command.
7. Open a block in the old folder. Select all the rungs in the block using the Edit -> Select All command. Copy block to the clipboard. Go to the new folder. Paste contents into the corresponding empty block of the new folder.
8. Repeat step 7 for all blocks in the old folder.
9. For External C Blocks, create the new block in the folder using the New Block... command and re-import the .exe file to the folder.
10. Rebuild the new folder and verify that contents are correct.

4. Communications and Online Monitoring

- CIMPLICITY Control, Version 2.1, supports SNP and Ethernet (TCP/IP) communication with the PLC. For SNP connections with 90-70 CPUs earlier than release 6.0, communication must be disconnected in the folder before a connection can be made to the fault tables.
- When storing hardware configuration via Ethernet (where the configuration information for the Ethernet module has changed), PLC communication will disconnect and reconnect. At this time, the privilege level is always set at the lowest level.
- When storing hardware configuration to a 90-30 351 or 352 CPU using SNP connected to the ECSM port on the CPU module (not the port on the power supply), an error will be reported at the end of the store and CIMPLICITY Control will temporarily lose communications. This happens because the CPU resets the port at the end of the store. To determine if the store was truly successful, you should check the details of the stored items for failures.
- If you are online and equal with a 90-70 PLC, any changes in logic will cause that block to go to the Not Saved state. Only the folder copy of the block has been changed and there will not be any prompts before the change is made. If the change is intended, you can select Store Program Changes from the right mouse button menu (or press ALT-S) to compile and send the changes to the PLC. If the change is not intended, you must close the block without saving to abort the changes. If the PLC is a 90-30 and the change is a single word change, it will go through the Word-for-Word change process, allowing you to abort the change or send it directly to the PLC.

5. Software Compatibility

CIMPLICITY Control supports the creation of C program blocks and standalone C programs for both the Series 90-70 and 90-30 PLCs. This capability requires use of the C Programmer Toolkit (IC691SWP709 and IC691SWP719).

To use C programming on the 90-30 requires CPU Version 8.00. To use C programming on the 90-70 requires additional files for the toolkit. Call GE Fanuc PLC Technical Support for more information:

USA and Canada..... 1-800-GEFANUC (1-800-433-2682)
All other Nations..... 804-978-6036

6. Importing Logicmaster 90-70 Folders into CIMPLICITY Control

CIMPLICITY Control provides the capability to import Logicmaster 90-30 351 or 352 folders, version 4.0 or higher, into CIMPLICITY Control. (Logicmaster 90-30 folders created prior to Version 4.0 must be updated to Version 4.0 before attempting to import.)

CIMPLICITY Control provides the capability to import Logicmaster 90-70 folders, version 4.0 or higher, into CIMPLICITY Control. (Logicmaster 90-70 folders created prior to release 4.0 must be updated before attempting to import.)

CIMPLICITY Control's rules about variable, block and program names differ from those for Logicmaster 90. To minimize the time required to prepare the Logicmaster 90 folder and reduce the errors generated during the import operation, make sure the Logicmaster 90 block names and nicknames conform to the following rules:

- Variable names and block names cannot contain the following characters:

double underscore	#	+	-	@
<	>	=	&	%

A variable name (nickname) that contains any of the characters listed in the above table will be considered invalid. Application folders should be reviewed for accuracy prior to import. Any invalid variable names will be discarded, and the reference address will be used instead.

- Variable names may not be used as program or block names. All block names must also be changed to be compliant with the naming restrictions before being imported.
- The following set of reserved words may not be used as variable, program or block names. In addition to the reserved words, function block names are also reserved words, and may not be used as variable, program or block names.

ACTN1, ACTN2, ACTN3 ...	ACTION	AND
ARRAY	AT	ADD
BODY	BY	BWAND
ANALOG_STATE	BOOL	BOOL_STATE
BWOR	BWXOR	BYTE
CONN1, CONN2, CONN3 ...	CASE	COMMENT
CONFIGURATION	CONSTANT	
DATE_AND_TIME	DELAY	DESCRIPTION
DINT	DO	DWORD
EDGE	ELSE	ELSIF
EN	END (invalid for 90-30 only)	END_ACTION
END_CASE	END_CONFIGURATION	END_FB_INTERFACE
END_IF	END_PROGRAM	END_REPEAT
END_RESOURCE	END_SEL	END_SIM
END_STEP	END_STRUCT	END_TRANSITION
END_TYPE	END_VAR	ENO
EXIT		
FALSE	FB_INTERFACE	FOR
FROM	FUNCTION	FUNCTION_BLOCK
FUNC_INTERFACE	IF	INITIAL_STEP
INT	INTERVAL	JUMP
LANGUAGE	LREAL	MACRO_STEP

MCR	MOD	NOT
OF	ON	OR
PRG_INTERFACE	PRIORITY	PROGRAM
PTR	READ_ONLY	READ_WRITE
REAL	REPEAT	RESOURCE
RETAIN	RETURN	RPTR
SEL_BRANCH	SIM_BRANCH	SINGLE
SINT	STACK_SIZE	STATIC_DATA_SIZE
STEP	STRING	STRUCT
SUMMARY	SUB	STEP1, STEP2, STEP3, ...
TRANS1, TRANS2, TRANS3, ...	TASK	THEN
TIME	TO	TRANSITION
TRUE	TYPE	TYPE_EXTERNAL
UDINT	UINT	USINT
VAR	VAR_ACCESS	VAR_EXTERNAL
VAR_GLOBAL	VAR_INPUT	VAR_IN_OUT
VAR_OUTPUT	VOID	WHILE
WITH	WORD	

Note

The Logicmaster Import function has been extensively tested. However, there may be cases where the logic in very complex rungs does not import correctly. Error messages in the output log stating “Dangling Horizontal”, “Illegal Rung Topology”, “Dangling Vertical”, or “Internal Error - Unable to Draw Rung Properly” should normally appear upon a compile of the folder if any problems were encountered. However, it is recommended that you print and review the logic after importing the folder.

Check the GE Fanuc BBS CIMPPLICITY Control area for more detailed information on importing Logicmaster folders.

7. LD Compatibility with Logicmaster 90

CIMPPLICITY Control has an option setting that facilitates sharing Ladder Logic PLC programs between Logicmaster 90-70 and CIMPPLICITY Control. This option is not necessary for the 90-30 since programs created are compatible unless you create rungs that extend beyond 10 columns. When you use CIMPPLICITY Control in LM90 Compatibility mode for a 90-70 folder, you can store a folder to the PLC and load it into either Logicmaster 90 or CIMPPLICITY Control.

Using Logicmaster 90-70 Version 6 or later or Logicmaster 90-30 Version 4 or later, you can upload a CIMPPLICITY Control-created RLD program from the PLC into the TEMP folder (or an equipment folder with a name that matches the program name in the PLC). Logicmaster will indicate an EQUAL status and be able to monitor activity in the PLC.

Likewise, CIMPICITY Control will be able to upload a Logicmaster 90 created RLD program from the PLC and go ONLINE and EQUAL. You will be able to make changes to the program and update the program without having to STOP the PLC.

The Compatibility mode can be activated from the Workbench. With the Browser window selected, go to the Tools menu, select Options, then select Equipment Folder. The Equipment Folder Options dialog box allows you to enable or disable LM90 Compatibility. The default is Disabled. (The setting will automatically default to Enabled during folder import conversion of an LM90 folder to CIMPICITY Control).

The following notes also apply to Logicmaster 90 compatibility:

- Blocks must be less than 16K bytes. A compile error will be issued when in LM90 Compatibility mode if the block exceeds the limit.
- Warnings will be generated when double-wide precision instructions or Calls do not have adequate spacing for the CIMPICITY Control display format.
- When loading a program from the PLC that was created with Logicmaster 90, you do not have to compile the program loaded into CIMPICITY Control unless changes are made after the load into CIMPICITY Control.

8 SFC Compatibility with Logicmaster 90

Folders that contain SFC blocks created with CIMPICITY Control are not compatible with Logicmaster 90. You should not attempt to use Logicmaster 90 with a PLC that contains SFC blocks created with CIMPICITY Control. For 90-70 folders, SFC blocks will not compile (an error will be placed in the log) if LM90 Compatibility mode is enabled.

Some simultaneous and selective constructs that were allowed in Logicmaster 90 are restricted in CIMPICITY Control in order to maintain IEC Compliance. You will need to edit the Logicmaster 90 folder before importing it into CIMPICITY Control.

Logicmaster 90 connectors will be changed into directed links during import into CIMPICITY Control.

New Features Introduced in Version 2.1

1. **Genius® Redundancy** - Version 2.1 introduces support for Genius Dual Bus Redundancy. This feature supports five types of redundant configurations: (1) Genius Dual Bus Redundancy with the redundant bus in the same folder (GBC Pair Internal), (2) Genius Dual Bus Redundancy with the redundant bus in another folder (GBC Pair External), (3) Genius Dual GBC Redundancy with the redundant GBC in the same folder (GBC Pair Internal), (4) Genius Dual GBC Redundancy with the redundant GBC in another folder (GBC Pair External), and (5) Genius Dual Bus and Dual GBC Redundancy.
2. **CPU Redundancy over Genius** - The following redundant CPU models will be supported:
IC697CPU780 Redundant CPU Expandable Memory (386)
IC697CGR935 Redundant CPU 1MB Fixed Memory (486 DX4)

Two types of control strategies will be allowed in the CPU Redundant systems: (1) Genius Hot Standby Control, and (2) Genius Dual Bus Control (not supported in CPU780).
3. **Single View of a CPU Redundant system** - Version 2.1 adds as part of the CPU Redundancy support, the ability to configure an entire redundant system within a single folder. The folder contains the configuration for both the Primary and the Secondary systems inside of the same folder. Modules can either be configured to be the same in each system or different. The program logic in both system must be identical. If either the logic is required to be different in the primary and secondary units, then separate folders are required.
4. **Ethernet Routing Configuration** - Version 2.1 adds the capability of configuring a routing table for the Type II Ethernet module in the 90-70 system. The existing CIMPILITY Control Name Resolution dialog has been enhanced to include a **Routing** tab to allow routing to be configured for 90-70 Ethernet Modules.
5. **Simple Network Time Protocol (SNTP)** - Version 2.1 adds the capability of configuring SNTP for the Type II Ethernet module in the 90-70 system.
6. **Increased 90-70 Ethernet Global Data Exchanges** - Version 2.1 enhances Ethernet Global Data exchange configuration by increasing the number of exchanges that can be from 32 to 255.
7. **Programmer Toolkit Extensions** - Version 2.1 adds new capability to Programmer Toolkit. The Application Programming Interface has been enhanced to provide import of variables from a Shared Name File (SNF) format into a specific equipment folder. The API will support Insert, Replace, and Delete attributes for importing variables.
8. **90-30 Profibus Configuration** - Version 2.1 adds 90-30 Configuration of 2 Profibus modules: IC693PBM100 Profibus Master Module, and IC693PBS105 Profibus Slave Module.
9. **Modem Dialing and Communications for the Serial SNP Protocol** - The Communications Configuration Utility will be modified to allow the customer to enter information about the modem they wish to use and then associate the modem definition with a device or port configuration. When connecting to a modem device or using modem port, the driver will automatically dial the appropriate number, initiate the connection with the host, and read/write data to/from the PLC using the modem connection.

New Features Introduced in the Version 2.01 Upgrade also included in 2.1

1. **Hardware Configuration for the Series 90-30 Model 350 and 360 CPUs** - Version 2.01 added the capability to configure the following 90-30 CPU models:

Release 8.10 CPU360 - IC693CPU360 Series 90-30 CPU Model 360 and
Release 8.10 CPU350 - IC693CPU350 Series 90-30 CPU Model 350

CPU 360

Identical Functionality to a Release 8.0 CPU351 except it does not have ESCM support.

Available memory for user programs is 80K.

CPU 350

Identical Functionality to CPU360 (Release 8.10) except memory available for user programs is 32K.

2. **LD and SFC Programming for the Series 90-30 Model 350 and 360 CPUs.** The 350 and 360 models function identically to the 351 and 352 models for programming. Note: Floating Point is not currently available in Model 350 and 360 CPUs

Problems Resolved in Version 2.1

1. **Loading of Logic Immediately after a Word-for-Word change has failed or been aborted no longer causes the changed block to be empty.** The problem where a load from the PLC caused an empty block after that block had been edited is fixed in Version 2.1. This problem most often occurred after a word-for-word change was aborted, but could also occur in other cases where an edit occurred while on-line and equal and a load was performed immediately after the edit.
2. **Warnings are now generated if overlapping addresses are configured using the Genius Configuration Tool.** The problem where warnings were not generated if overlapping addresses are created using the Genius Configuration Tool has been corrected in Version 2.1.
3. **Hitting <ENTER> during Auto-Select no longer causes communications errors.** The problem where aborting the Auto-Select by hitting <ENTER> sometimes caused “Unknown Communications Error” messages has been fixed in Version 2.1.
4. **Rungs of the following form in 90-30 folders will no longer cause CIMPPLICITY Control to crash on Load from PLC.** Rungs that logically attempt to get more than 8 deep OR branches no longer cause CIMPPLICITY Control to crash on a Load. These rungs are illegal rungs for 90-30 LD that are not flagged as illegal during Save and Compile.




The decompiler will now place entries in the log file whenever rungs of this type are encountered on a load. These rungs still must be manually corrected in order for a load to correctly work.

5. **Help has been updated in Version 2.1 to address two issues:**

A better explanation of how to select more than one variable in the Variable Declaration Editor and the index has been updated so that searching on the key word “Retentive” will find the correct topics.

Problems Resolved in Version 2.01 also resolved in Version 2.1

1. **Incorrect Logic Solution:** Version 2.0 Service Pack 3 and Version 2.01 corrects a problem with logic solution in Series 90-30s using CIMPPLICITY Control. RLD programs with the following construction will not solve correctly if stored with Version 2.0. Refer to Field Service Bulletin M-04-98-01 "CIMPPLICITY Control Release 2.0 Safety Alert" for more information.



To fix this problem, install Version 2.01 and then do a Rebuild All of each CIMPPLICITY Control Series 90-30 folder.

2. **Update PLC Button for PID Dialog:** Using the Update PLC Button of the PID dialog box causes a value of Zero to be written to CV. The Update PLC Button has been disabled in CIMPPLICITY Control Version 2.0 Service Pack 2 and higher.
3. **Length of Genius Global Data set incorrectly after Save:** Service Pack 1 corrects a problem with the configuration of Genius Global Data for the Series 90-70 where the length was incorrectly updated on a Slave.
4. **Intermittent Communications Errors:** Intermittent communications problems, primarily occurring during connect and store to PLC have been corrected.

Restrictions and Open Problems

Communications

1. **Time-outs may occur during a store using SNP.** It is possible to lose communications intermittently during a store operation over SNP. The problem may be experienced with very large programs, or if running CIMPICITY Control on a PC with little available RAM. To reduce the likelihood of this problem occurring, limit active applications during the store, or add additional RAM. If you experience this problem, repeat the store operation.
2. **Saving folders to Novell drive.** Saving folders to Novell drives that require an 8.3 format is not supported. You must use the newer version of Novell which supports longer filename suffixes.
3. **Performance tip.** For best performance when using the "Store Program Changes" (ALT-S) or Word-for-Word changes feature, you should, upon opening a folder, perform a build using the Rebuild All command. This will allow subsequent Store Program Changes or Word-for-Word changes to occur faster.
4. **Method to expand Target Communications Window (right click on title bar) is not obvious.** To expand this window so that you can view detailed information, click the right mouse button in the title bar of the Target Communications window.
5. **Synchronizing CPU time to Host may cause Run and Stop buttons to display incorrectly for a few seconds.** To correct this problem, disconnect from the PLC and then reconnect.
6. **Fault table continues to show faults after connection with PLC is terminated.** It is not possible to clear the fault table screen when disconnected. To clear any messages logged in the fault table, you will have to reconnect to the PLC.
7. **Error message on trying to connect to wrong CPU type does not indicate if the type (70 or 30) or the model (351, 352, etc.) is wrong.** The message only indicates that a mismatching CPU was detected.
8. **Incorrect error message.** Disconnecting the communications cable from the PLC for an extended period of time can randomly make the message "Maximum number of users for requested port has been reached" appear. Exiting CIMPICITY Control and re-entering may be required to reconnect to the PLC.
9. **Storing block and configuration information in same attempt through 9030 Serial Port #2 may fail.** This has been observed on a 351 CPU, storing program and configuration information, and seems to happen whether or not the new configuration information is actually different or not.
10. **Cannot connect to PLC if both Genius busses in a Dual Bus/Internal Configuration are open.** Close one of the busses to perform the connect.

Hardware

1. **Confusing error messages may be generated in the Ethernet Global Data dialog box.** Be sure to finish configuring Status variables in the Produced Exchanges tab before switching to the Consumed Exchanges tab.
2. **Copying and pasting a Type 2 Ethernet module from one folder to another does not copy and paste EGD and Name Resolution entries.** After performing a paste, you will need to go to the Ethernet Global Data and Name Resolution menu items and enter the values manually.

3. **Storing HWCFG does not store Genius configuration to blocks and there is no message telling you block configurations are not being stored.** You should store the configuration from the Genius Configuration tool (accessed by choosing Expand Bus from the right mouse button popup menu). You will need to open the Genius Bus objects one at a time and store them.
4. **Reference Addresses on Hardware Modules - drag and drop changes them.** If you manually change the reference addresses of modules to overlap, and then dragged one of the overlapping modules, the module (on insert or drag) re-evaluates the reference address to make sure it is not conflicting. Since the module is overlapping, it resets the address to the next available location to remove the conflicting range.
5. **9070 CPU diagnostic/fault categories go back to defaults when CPU type is changed.** You will need to reset these categories manually if you wish to have the settings restored.
6. **Can't set Constant Sweep higher than 2550 milliseconds.** The constant sweep time cannot be set higher than the Watchdog Timer, which has a limit of 2550 milliseconds.
7. **Storing Central Rack System or Ethernet Global Data by itself eliminates Name Resolution.** Storing the Central Rack System or EGD configuration by itself without selecting the Name Resolution erases the Name Resolution file from the PLC. Always select the Name Resolution data if it has been configured, when storing any other part of Hardware Configuration.
8. **Pasting a Genius bus to the browser then double clicking on it causes Fatal System Error.**
9. **Configuration does not verify equal after storing a 350 or 360 configuration to a 351 / 352 CPY.** Storing a 350 or 360 configuration to a 351 CPU results in configuration not equal. Change HWCFG to 351 to fix.
10. **Browser focus can get confused on Genius Dual Bus.** Browser can get confused as to which bus the primary or the starred should have focus. Leave the browser and return to fix the focus
11. **APU301 allows range for EOT in follower mode.** Range should be fixed at +8388607 and -833608.
12. **Name Resolution and EGD files missing Type 2 Ethernet adapter name in redundancy mode.** The Type 2 Ethernet adapter should have separate names in the primary and backup. Only the last name entered appears. This does not cause operational problems.
13. **Aborting Clear of a large folder in 90-70 PLC may cause Fatal System Error on Windows 95.** After Storing to a 90-70 PLC a program of substantial size, containing name resolution and EGD, if the PLC is cleared using the Utilities Clear Dialog, a Fatal System Error may occur when running on Windows 95, if the clear operation is aborted prior to completion.
14. **After a Load of Hardware Configuration, if the Network Address Name field is edited before the Adapter Name has be redefined on the Ethernet Global Data dialog, it will be impossible to exit from the dialog.** This problem can be avoided by re-entering the Adapter Name after the load before editing any other fields in the EGD dialog. If the Network Address Name field is accidentally edited first then CIMPICITY Control must be killed through the task manager.

Workbench

1. **Save As function.** Premature termination of the product may occur if you attempt to do a "Save As" function to a disk (floppy disk or hard drive) that has insufficient space. To avoid losing work, be sure your disk has the recommended space available.
2. **Losing track of active windows from menu.** You may not be able to see all the active windows in the list displayed from the Window menu. Active windows can still be found on the screen.

3. **The Save Changes dialog only appears in the Equipment Folder when the folder is first created.** The Save Changes dialog box appears the first time you close an equipment folder after it has been created. Operations such as Delete and Cut will not cause the Save Changes dialog to be displayed. If you create a new folder and exit, you will be prompted to save the equipment folder. However, if you create a new folder, insert some blocks, and then delete a block, you will not be prompted to save, because the deletion saves the folder automatically.
4. **Drag and drop in the browser will not scroll to allow drop on the part of the browser that needs to be scrolled to be seen.** To avoid this problem, use Cut and Paste instead.
5. **Save As does not work to server name for networked drives.** You should map the drive to a letter.
6. **Importing a block from the Librarian does not include the blocks that the imported block calls.** You will need to manually import blocks that are called, or create temporary blocks with the same names as those being called.
7. **Fatal System Error may occur when opening another instance of CIMPLICITY Control with a library file.** If you create a new library file, save it, and close the library file while leaving the Workbench active, and then start another instance of CIMPLICITY Control and open the same library file again, a fatal system error may occur.
8. **Installation sometimes gives error message COMCTL32.DLL is locked when installing on Windows 95.** This is because there is program that is accessing this DLL. Close all other programs and restart the installation.


Logicmaster Compatibility

1. **Folder conversion of HEX constants.** Constants programmed as HEX and displayed as HEX in Logicmaster 90 will display in decimal format after importing or loading the folder into CIMPLICITY Control.
2. **Logicmaster 90 and CIMPLICITY Control with the same COM port.** After using Logicmaster 90, you must reboot your computer before attempting to use CIMPLICITY Control with a serial connection to the same port that Logicmaster 90 used. If you do not reboot, you will receive an error message stating that the requested COM port could not be opened.
3. **Folders created in Versions 1.0 and 1.1 will not compile Array Move instructions.** You must adjust the *SNX*, *DNX*, and *N* operands because their data type has changed from INT to UINT.
4. **A type cast of a variable located in %P memory that specifies a length that extends beyond the last variable located in %P will cause the size of the %P table to be incorrect.** Execution of a folder that has this problem will cause the CPU to Stop/Fault with Error message of Program References exceed those configured in PLC. To correct this, a variable should be declared that is located at the end of the type-casted array variable.
5. **Hardware Configuration for 90-70 that contains Genius Global Data will not be able to be loaded by LM90.** The Hardware Configuration data downloaded to the PLC when Genius Global Data is configured is not compatible with Logicmaster 90-70 and therefore cannot be uploaded into a Logicmaster folder.


Software Resource and Programming

1. **Floating-point instructions.** If the CPU is changed from a non-floating point to a floating point CPU while the LD Editor is open, instructions requiring a floating-point CPU will not display. To view these instructions, close and re-open the LD Editor.

2. **Parameter Edit dialog box.** The Parameter Edit dialog box allows 64 characters for the description field, but will display only 57 characters from the Header dialog box.
3. **Seventy or more transitional contacts in same rung.** If using 70 to 80 transition contacts in the same rung in Accept or Normalize mode, premature termination of CIMPACTY Control may occur which will cause you to lose changes since your last Save.
4. **Deleting all instructions in a rung does not delete the rung.** To delete a rung, you must select the rung by clicking to the left of the power rail and then delete the rung.
5. **Complex 90-30 Boolean rungs failing on compile.** Some 90-30 complex boolean rungs, such as the one in the following example, fail on compile. The error message “Logic sub-path cannot enter in the middle of another sub-path” is generated.



To work around this problem, insert an ALW_ON contact as a placeholder in the logic, as shown in the following example.



6. **Copying and pasting rungs from SFC to LD.** You cannot copy and paste rungs from an SFC block to an LD block or from the terminal LD editor in SFC to an LD block. However, you can copy from an LD block and paste into the terminal LD editor within an SFC block.
7. **Move instructions in 90-30 Equipment Folders.** In a 90-30 folder, inserting a Move instruction without enough space between it and the next Move results in data flow from output of first move to input of second move which is not allowed in a 90-30. To avoid this, add sufficient space between Move instructions to allow the operands to appear. To adjust the placement of the Move instruction, click once on the Move instruction, cut the instruction, and paste it farther away from the preceding Move instruction.
8. **Footer problem when printing Use Table from a block.** Printing Use Table from a block results in the footer displaying a block name when it should not.
9. **Variables that are type cast to a larger data type are not found as implicit use in Search.** You must search directly for the reference address if it is type cast in an editor.

10. **Zoom size change does not work if Zoom is typed into LD Edit control.** Click the pull-down control for the combo box so that all the entries are displayed (75%, 100%, 150%, etc.). Now type the desired Zoom size into the box and press ENTER with the pull down list still open. The Zoom size should now be properly reset. An alternate way of setting the Zoom size is to choose Zoom from the View menu.
11. **In LD Editor, data entries which are not completed are lost if you click outside the LD Edit window.** Be sure to complete a data entry before clicking outside the LD Editor.
12. **The LD Editor gives an incorrect output messages.** If you insert a named variable of local scope with an address and then use the same name in LD logic, but you give it Configuration scope and no address, you will receive an incorrect error message, "Variable and called block have the same name". If you give a Data Init instruction a length that is too large, the error message given is "Invalid Array Operation".
13. **PSB Bool Parameters are allowed as actual parameters.** PSB parameters of type BOOL are incorrectly allowed to be passed as actual parameters to other PSB or External Blocks. This should not be allowed since the PLC does not support this.
14. **Pasting a rung with a call to a "C" block into a folder where the type of the block is a PSB, does not correct the call instruction.** If a rung with a call to "C" block from one folder is pasted into a second folder where there is a PSB with the same name and same parameters, the rung will incorrectly continue to show the call as CALL EXT. To correct, delete and replace the call in the rung.
15. **Use of %S32 (continuation) directly as an operand may cause programs that compile correctly to not be able to be uploaded in the 90-30.** If the %S32 reference address is programmed on contacts directly, a program that has been compiled and downloaded to the PLC, will fail on the decompile after a load. Use of %S32 directly should be avoided. The continuation coil and continuation contacts should be used instead.

Variables

1. **Error message during Auto-Variable Location.** When an error occurs using auto-variable locate, the error message is general. The conditions are that the configured references have been exceeded or that the range for auto-variable location has been exceeded. To view the range used for auto-variable location, expand the Browser until the Resource is displaying in the left side of the Browser window, then double-click Resource to open the Resource Editor. From within the Resource Editor window, select Program from the CIMPPLICITY Control menu and choose Auto Variable Locate.
2. **Selecting multiple items in Variable Declaration editor.** You must use the keyboard to select multiple variables in the editor.
3. **Deleting the reference address on a variable causes the scope to change to local.** If you leave this variable in local scope, you will have compile problems if the variable is used in other blocks as a Config variable. To prevent these problems, change the scope back to Config.
4. **Deleting variables at the Local Scope.** If the same variable name exists at Local and Config scopes and the local scope one is used, the Config Scope one can not be deleted from the Block Editor window. You can, however, open the Config Scope editor and delete the variable name from there.
5. **Default length of a new variable might be set to values other than 1 after inserting arrays.** To correct this, examine the length field and change it if necessary.
6. **Find in Reference Table that jumps to end does not clear the bottom on the screen.** Scroll the screen to cause a refresh.

7. **Global Use Table Printout does not show overlaps in bit type Tables when 16 or 32 bit types overlap Bools.** Example Int at %G1, Bool at %G5, overlap is not shown for %G5.
8. **Changing a local variable in one VarDec splitter causes all open VarDec splitters to go “not Equal”.** Closing and reopening the editors for the other blocks will correct the problem.
9. **Descriptions of Variables do not wrap in a consistent manor when displayed in LD Editor.** The wrapping of long descriptions is based strictly on the default wrapping supplied by the Windows underlying controls. The convention used in LM90 is not observed.
10. **Using Online Edit Dialog on Structure Variables (e.g. Timer.CV) causes CIMPICITY Control to crash.** Use of the Online Edit Dialog on variables that reference fields inside of a structure, such as the CV of a timer, will cause CIMPICITY Control to crash. If the direct in-place edit of the online value is used instead CIMPICITY Control will operate correctly.

Redundancy

1. **Genius Output transfer check not performed.** CPU redundancy is supposed to check that all Genius outputs and being transferred and warn if they are not. This check is not done. The check needs to be done manually.
2. **Fatal System Error closing objects in browser.** In Dual Bus/ External mode if an object is inserted in the browser, changing views or closing the object causes a Fatal System Error.
3. **Equality not displayed correctly with CPU Redundancy.** When using CPU redundancy in “Single View” mode, even though both CPUs are configured identically, only the view of the Hardware configuration for the CPU to which one is attached will show equal. If the programmer is attached to the Primary CPU then the view of the Secondary configuration will show “NOT EQUAL” and visa versa.
4. **Genius Bus must be expanded before proper configuration can be created for Redundant Controller and Dual Bus.** After a GBC has been created, the bus must be expanded at least once, even if there are no blocks to be configured in order for the redundant Bus Controllers to be properly configured.