

# IMPORTANT PRODUCT INFORMATION

## READ THIS INFORMATION FIRST

**Product: Series 90™-70 PLC CPU with Firmware Version 7.85**

**IC697CGR772-EA  
IC697CGR935-GB**

This document contains information that is not available in any other publication; therefore, we recommend that you read and save it for future reference. This document discusses the features of the IC697CGR772 and IC697CGR735 CPUs with firmware version 7.85.

This release updates IC697CGR772 and IC697CGR735 hardware. The hardware change replaces four obsolete programmable logic devices (PLDs).

## Version Identification

### Hardware Identification

The following table shows the revision level of the circuit boards used in this release of the CPU.

<i>CPU</i>	<i>Board Identification</i>	<i>Board Revision</i>
IC697CGR772-EA	CPXA1	44A739520-G01R08 or later (motherboard)
	HPMC1	44A751230-G01R01 or later (daughter board)
IC697CGR935-GB	CPXA1	44A739520-G01R08 or later (motherboard)
	CMVC1	44A749536-G01 Rev 01 or later (daughter board)

### Firmware IDs

<i>CPU</i>	<i>Board</i>	<i>Location</i>	<i>FW Version</i>	<i>Check Sum</i>	<i>Part Number</i>
IC697CPX935-GE IC697CGR772-EA	CPXA1 / CPXB1	U30	7.60	0784BF8F	44P725986-409A
		U47	N/A	5DCB	44P725580-103A
		U58	N/A	D801	44P725580-104A
		U74	N/A	F873	44P725580-105A
		U79	1.00	058B1650	44P725986-410A
IC697CGR772-EA	CPXA1	U6	N/A	BFF7	44P723409-109A
IC697CGR935-GB	CPXA1	U6	N/A	B499	44P723409-110A

### Firmware Upgrade Kit

To upgrade previous versions of IC697CGR935 to firmware version 7.85, you must purchase the field upgrade kit 44A747170-G01 or download it at no charge from the web at <http://www.geindustrial.com/cwc/gefanuc/support/ControllersIO/s9070-u.htm>. (The initial release of IC697CGR772 includes firmware version 7.85.)

## Functional Compatibility

The new version of the CPU module is functionally compatible with previous versions.

## Product Documentation

The following documentation is available for the IC697CGR772 and IC697CGR735:

*Series 90-70 CPU Reference Manual*, GFK-0265

*Series 90-70 PLC Installation Manual*, GFK-0262

*IC697CGR772 Data Sheet*, GFK-1437

*IC697CGR935 Data Sheet*, GFK-1439

## Special Operational Notes

### Programmer Version Compatibility

**CIMPLICITY® Machine Edition Logic Developer – PLC** version 2.11 or later, **VersaPro™** version 2.02 or later, **CIMPLICITY Control** version 2.40 or later, or **Logicmaster™ 90-70** version 7.02 or later should be used to configure and program IC697CPX772. The following restrictions apply:

- **CIMPLICITY Machine Edition Logic Developer – PLC** version 2.11 or later, **VersaPro** version 2.02 or later, or **CIMPLICITY Control** version 2.20 or later is required to support Serial Ports 1 and 2, User Flash Memory, Ethernet Global Data, I/O Scan Sets, VME 3rd Party Interrupts, and Bulk Memory Access.
- **CIMPLICITY Machine Edition Logic Developer – PLC** version 2.11 or later or **CIMPLICITY Control** version 2.20 or later is required to support Parameterized Subroutine Blocks (PSBs), Remote Genius I/O Configuration, Stand Alone C Programs, and Multi-threaded LD Programs.
- **CIMPLICITY Control** version 2.20 or later is required to support Sequential Function Chart (SFC) programming, FIP Configuration, and Clock Synchronization using FIP.
- **Logicmaster 90-70** version 7.02 or later supports Serial Ports 1 and 2 and User Flash Memory, but does not support Ethernet Global Data, I/O Scan Sets, or VME 3rd Party Interrupts.

### PCM and BTM Compatibility

With the timing improvements and new features first made available in 90-70 Release 5.00, it is highly recommended that systems using PCMs use IC697PCM711J or later. It is also highly recommended that systems using BTMs use IC697BEM713B or later. Use of boards of an earlier revision may result in lower system performance.

### PCM (to CPU) Communications Timeout

The PCM711 with firmware version 4.01 and earlier has a default backplane communications timeout value of 5 seconds. After the PCM has sent a request to the 90-70 CPU, the PCM applies this timeout while it is waiting for a response back from the CPU. In most cases the 90-70 CPU will respond well within the 5-second timeout. However, in certain cases the 90-70 CPU can take longer than 5 seconds to respond. (These cases are limited to LOAD/STORE operations of program and/or configuration, especially when blocks in the program are larger than 8K bytes. Folders containing EXE blocks (again, with \*.EXE files > 8K bytes) are most likely to present problems. Beginning in release 6.00, Standalone C programs larger than 8K bytes also cause this scenario.)

Beginning in release 5.50 of the 90-70 CPU, the CPU is guaranteed to respond within 8 seconds. Beginning in release 4.03 of the PCM711, the default backplane timeout is 10 seconds. To ensure that PCMs with release 4.01 and earlier firmware do not observe backplane timeouts, a file must be loaded (using *termf*) to the PCM. The file is a binary file and must be named "CPU.ENV." The contents of the file are (all values specified in hexadecimal):

GFK-1440D

File Offset	DATA
0000 4C 5A 01 01 00 00 00 00-00 00 00 00 01 00 00 00	LZ.....
0010 00 00 00 00 00 00 00 00-00 00 43 50 55 4C 49 4E	.....CPULIN
0020 4B 2E 43 4F 44 00 2D 62-00 36 34 00 2D 74 00 32	K.COD.-b.64.-t.2
0030 30 30 00 00 43 50 55 4C-49 4E 4B 2E 44 43 42 00	00..CPULINK.DCB.
0040 00 4E 55 4C 4C 3A 00 4E-55 4C 4C 3A 00 4E 55 4C	.NULL:.NULL:.NUL
0050 4C 3A 00 00 00 00 00 00-00 00 00 00 00 00 00 00	L:.....
0060 00 00 00 00 00 00 00 00-00 00 00 00 00 00 00 00	.....
0070 00 00 00 00 00 00 00 00-00 00 00 00 00 00 00 00	.....

Once the binary file CPU.ENV (above) is created, use *termf* to load CPU.ENV to the PCM. Then execute a soft reset of the PCM. After executing the soft reset the PCM's backplane communications timeout should be 10 seconds.

**Note:** A copy of the above CPU.ENV file can be obtained from the technical support web site.

**CAUTION**

**The CPU.ENV file will not be used when a hard reset is performed on the PCM. With the CPU.ENV file resident in the PCM, a soft reset must be performed after every hard reset of the PCM. Please note that it is possible to issue a "soft reset" COMM\_REQ from the Ladder Diagram application; therefore, the application can be modified to handle the required soft reset of PCMs after a power cycle of the PLC system.**

**Notice to Update GBC Firmware**

With the introduction of new features in CPU release 5.00, timings with the Genius Bus Controllers (GBCs) changed; this uncovered a problem in the GBC firmware. GBCs on expanded racks could be lost if the system is fully configured and only the main rack cycles power.

Also, in previous versions of the GBC there was a problem with input data coherency. In a system with a large CPU sweep time and a short Genius bus scan time a problem could be seen if a device is lost. Input data could be defaulted off while the CPU is reading the data from the GBC.

It is recommended to update existing GBC hardware to IC697BEM731M or later when updating the PLC CPU firmware to release 8.00. Operation of the IC697BEM731M, in conjunction with release 8.00 of the 90-70 CPU, will result in a slight impact to the I/O scan time of the 90-70 PLC.

**3rd Party VME Modules**

Logicmaster 90 Release 5 (and later) allows 3rd Party VME modules to be configured for six modes: NONE, INTERRUPT ONLY, BUS INTERFACE, FULL MAIL, I/O SCAN, and REDUCED MAIL. However, CPU Release 7.92 does not support REDUCED MAIL.

**Maximum PLC Sweep**

In systems configured for Genius Bus Redundancy, a complete PLC sweep must be executed every 500 ms or less, even though it is possible to configure the watchdog timer to higher limits. This also means that resetting the watchdog timer with Service Request #8 cannot be done indefinitely.

## Serial Comm

The following operational restrictions exist for the Serial Communications feature:

1. Serial communications may add up to 5ms of time to any given sweep. This should be taken into account when setting the watchdog timer.
2. The following procedure is recommended when changing baud rates in the PLC and the WSI board. First enter the configuration package and change the baud rate on the PLC, then store the new configuration. Now power off the PLC and then go to the WSI setup screen and change the WSI baud rate. Finally, power the PLC back on.
3. The link idle time setting in the Hardware Configuration for Serial Communications should be set to 10 seconds or greater. Otherwise, a communications failure will occur when storing the configuration to the PLC.

## Serial Port Mode Configuration (Applies to Port 3 Only)

There is a serial port configuration parameter under software configuration for the PLC CPU called MODE. This configuration parameter can be one of two values: **SNP** to indicate that serial port 3 will be used for SNP communications, or **MSG** to indicate that the serial port will be used to send `printf` commands from a C block (or Standalone C Program) to the connected device. If MODE is configured to be **MSG**, and programming software or an HMI/SCADA device is also using port 3 as a means of communicating with the PLC, communications with the PLC will be lost when the PLC goes to RUN mode because serial port 3 is now configured for `printf` commands.

## LM90/WSI Attach

Do not connect or disconnect the WSI/BTM cable while the PC/Workmaster host is powered on. This action may cause a running PLC to Stop.

## Expansion Rack ID

The expansion racks for the Series 90-70 are shipped with the rack ID strapped for rack 0 (the main rack). If the rack jumper is not changed the PLC will not recognize the rack at all and may not properly identify the error.

## Expansion Rack Cable

Connection and disconnection of the expansion rack cable while the CPU is running should not be attempted. This will cause the PLC to go to the STOP/HALT state.

## Expansion Rack Power

Expansion racks should be powered up at the same time the main rack is powered up or they should be powered up after the main rack has completed its power up initialization. Do not power up an expansion rack while the PLC CPU is running power-up diagnostics.

## Memory Usage

A general rule-of-thumb for memory usage is 48 bytes per I/O point plus register memory in bytes.

## Timer Operation

Care should be taken when timers (ONDTR, TMR, and OFDTR) are used in program blocks that are NOT called every sweep. The timers accumulate time across calls to the sub-block unless they are reset. This means that they function like timers operating in a program with a much slower sweep than

GFK-1440D

the timers in the main program block. For program blocks that are inactive for large periods of time, the timers should be programmed in such a manner as to account for this catch up feature.

Related to this are timers that are skipped because of the use of the JUMP instruction. Timers that are skipped will NOT catch up and will therefore not accumulate time in the same manner as if they were executed every sweep.

### Fanuc I/O Link

When powering up the PLC CPU without a battery and Fanuc I/O Link boards are present, an incorrect "Loss of Module" fault will be logged for each Fanuc I/O Link board. The PLC CPU will not consider these boards as lost, and the boards will continue to operate properly.

### COMM\_REQs with Retentive Memory

When powering up the PLC CPU with a program being retrieved from Retentive Memory and proceeding to RUN Mode, any COMM\_REQs to a PCM should be delayed for 5 seconds.

### Constant Sweep

**Constant Sweep** time, when used, should be set at least 10 milliseconds greater than the normal sweep time to avoid any over-sweep conditions when monitoring or performing online changes with the programmer. The smallest valid constant sweep time setting is 10 milliseconds. Window completion faults will occur if the constant sweep setting is not high enough.

### Interaction of Programming Software with Closed Programming Window

Programming software cannot be used to change the PLC Sweep Modes or timers (Constant Sweep Time, Program Window Times, etc.) while the program window is closed. Use Service Requests #1 - #4 from the PLC application to perform these functions.

#### CAUTION

**Programming software cannot be used to change the PLC mode (STOP, RUN, etc.) while the programming window is closed. Use the toggle switch on the CPU module instead.**

### Model CGR772/CGR935 CPU Ambient Temperature

Due to the high power dissipation of the CGR772 and CGR935 CPU microprocessors, these modules' ambient temperature during operation must be kept at or below 50 degrees Celsius. With forced air cooling, 60 degrees Celsius is allowed.

Fan assemblies IC697ACC721 (120 VAC) and IC697ACC724 (240 VAC) are available for direct mounting to the Series 90-70 rack.

### SFC RESET Function Block

The SFC RESET function block only executes when used in Action Logic or Pre/Post Logic within an SFC block (Main SFC or SFC sub-block). Attempting to execute an SFC RESET function block from a Ladder Diagram Main/sub-block will not reset the SFC network and (as of v6.02) will not pass power flow to any logic right of the SFC RESET.

## Ethernet Global Data and Sweep Time

Each Ethernet Global Data exchange configured for either consumption or production can add up to 1msec to the sweep time. This sweep impact should be taken into account when configuring the PLC for constant sweep mode and setting the CPU watchdog timeout.

## CMM and PCM Module Compatibility

Due to the increased reference table sizes on the CPX CPU models, older versions of CMM and PCM modules may experience compatibility problems with the CPX model CPUs. Firmware upgrades are available for customers with other versions of these modules.

CMM modules (IC697CMM711) of revision 'F' or later will not experience this problem.

PCM modules (IC697PCM711) of revision 'P' or later will not experience this problem.

## Serial Ports 1 and 2

This CPU is equipped with two additional serial ports (ports 1 and 2) as well as the standard serial port (port 3) found on previous Series 90-70 models. Port 1 supports the RS-232 standard, and port 2 supports the RS-485 standard. These additional serial ports support the following baud rates: 1200, 2400, 9600, 19200, 38400, and 57600. Note that they do not yet support 115k baud. Both ports can be operated simultaneously without dropping characters up to 57600 baud.

SNP Slave protocol support for these ports was added in firmware release 7.80. Break-free SNP (slave) was added as the default protocol to ports 1 and 2 in firmware release 8.00 (port 3 does not support break-free SNP). All functionality of serial port 3 is available through ports 1 and 2 with these exceptions: (1) they do not support connection of the C debugger; (2) they do not support `printf` functionality for C programming.

All three serial ports can be configured by programming software to select baud rate, parity, stop bits, etc.

If upgrading this module from a previous version that did not support these two ports, you may have to set the ports' configuration parameters (using a programmer connected to port 3) before you will be able to use the ports.

## Programmer Communications Issues (Serial Ports 1 and 2)

When using serial ports 1 or 2 for programmer communications, a momentary loss of communications may be observed after a store of hardware configuration while configuration settings are being updated. This is normal operation. Port configuration changes for ports 1 and 2 are processed after the store of hardware configuration. Changes to the configuration of port 3 are processed on a reconnection of port 3.

Note that all port communications settings should be carefully verified before performing a hardware configuration store. If any of the essential configuration settings (such as mode, baud rate, parity, etc) for the port connected to the programmer are changed, you will lose communications after a configuration store. Communications will be restored once the host (programmer) settings are changed to match the port's new settings.

GFK-1440D

### Word-wide reads from a 3<sup>rd</sup> Party VME Module

An attempt to read a word value from a 3<sup>rd</sup> party VME module that does not support word-wide accesses will cause the module to generate a System Bus Error fault if it responds to a GE Fanuc slot-based address. This has the following implications:

1. The 90-70 CPU always interrogates the first several bytes of every GE Fanuc slot assignment using word accesses during system configuration. Accordingly, users may observe a System Bus Error fault from such a module immediately after power up.
2. If a System Bus Error fault occurs immediately after power up in a PLC that uses a 3rd party module, the user should determine whether that module does not support word-wide accesses, responds to a GE Fanuc slot-based address, and asserts bus errors. If the module has all these characteristics, then the bus error fault should be ignored. Designers of applications that use such modules should advise their users to ignore this fault.
3. To avoid this System Bus Error fault, designers of applications using 3rd party VME modules that do not support word-wide accesses should do one of the following:
  - (a) Configure the module so that it does not respond at all to word-wide access from the CPU. There are two ways to do this: 1) Configure the VME base address of the module in the range 100000 - 7FFFFFFF (hex) so that it is not at the beginning of any GE Fanuc slot-based address space; or 2) Configure the module to use Address Modifier code 3Dh rather than 39h or 29h. These are the preferred solutions and are often the easiest.
  - (b) Configure the VME module so that it does not assert BUSER. One possible way to do this is to disconnect the VME BUSER line from the module (which will force it high). However, this will not work if the module also asserts DTACK for these word-wide cycles.

## New Features and Functionality of Firmware Release 7.85

### List of New Features of Firmware Release 7.85

The following new features have been added in Release 7.85:

1. Ability to use Serial 1 and 2 for serial communications
2. Increased LD and C Program Size
3. Introduction of the IC697CGR772 CPU module

### Support for Serial Ports 1 and 2

Earlier releases of CPU firmware for the IC697CGR935 module supported Serial Port 3 but did not support Serial Ports 1 and 2, even though the port hardware was present. Firmware release 7.85 adds support for these two ports on the IC697CGR935 and also supports them on the new IC697CGR772. Port 1 uses the RS-232 standard, and Port 2 uses the RS-422/485 standard. Both of these serial ports may be used at the following baud rates: 1200, 2400, 9600, 19200, 38400, and 57600. Note that these ports do not yet support 115K baud. Both ports can be operated simultaneously up to 57600 baud without dropping characters.

Serial Port 3 is still the primary connection port for the serial programmer.

The SNP (Series Ninety Protocol) Slave protocol is the only protocol supported by Serial Ports 1 and 2 in firmware release 7.85. All services available through the standard SNP Port 3 are available through the new ports with these exceptions: you cannot do Store/Load of Logic and/or Configuration, and you cannot send Datagrams (Datagrams are the services by which the MS-DOS and Windows programming packages monitor reference table data and program animation).

The HMI software does use services other than Datagrams to monitor reference data, and these services are supported through these ports, so you could use the HMI software for monitoring data within the PLC.

Serial Ports 1 and 2 can be configured by both the MS-DOS and Windows programming packages for setting baud rate, parity, stop bits, etc.

### Increased LD and C Program Size

With firmware release 7.85, you will be able to store larger LD/SFC programs than previously to the IC697CGR935 CPU module. The following rules will apply in determining LD/SFC program charges:

1. Total memory used for programs, configuration, and reference tables in the CPU must not exceed the daughterboard size. Therefore, the LD/SFC program can never be larger than the daughterboard size.
2. The LD/SFC program can now be up to 544K (557,056 bytes) when the user's selected stack size is 12K or less (the default stack size is 12K and, therefore, the default LD/SFC program limit is 544K). The stack size is not counted against the 544K limit or the daughterboard limit in this case.
3. The LD/SFC program can now be up to 532K (544,768 bytes) when the user's selected stack size is larger than 12K. The first 12K of the user's selected stack size will continue to not count against the program or daughterboard limit; the remainder of the stack size will be counted against both program and daughterboard limits. For example, if the user selects a 20K stack, then 524K (532K – 20K + 12K) will be available for the LD/SFC program.
4. Memory needed to store the initialization constants for C Program Bloc data will no longer count against the LD/SFC program limit. They will, however, continue to count against the total daughterboard memory used. The user will also be able to now store Standalone C programs up

GFK-1440D

to 564K (577,536 bytes) including the stack when using daughterboards larger than 512K. For example, if the user has selected a 16K stack for the Standalone C program, then the program can be up to 548K (564K – 16K). The memory needed for initialization constants for the data will continue to be counted against the daughterboard size but not against the program limit. The IC697CGR772 module is limited to 512K bytes of user memory and will not be able to take advantage of the increased LD and C program sizes.

## Problems Resolved by Firmware Release 7.85

### When Using an Ethernet Module

The CPU would fail if Loss of Module or System Configuration Mismatch faults were logged against an Ethernet module. The failure only occurred if point faults were enabled in the CPU and the status word for the Ethernet Module was configured for %R memory. This failure has not existed in any CGR PLC releases.

### Loss of Option Module Faults

CPU logged two Loss of Option Module faults on the RCM when the Hardware Configuration was cleared.

### Masked Compare Function Block Usage

The masked compare function block did not operate correctly when the first input parameter (first bit string) was not aligned on a word boundary (e.g. %M0009 instead of %M0017). Using the masked compare function block in this way would access a byte in memory just before the MASK parameter resulting in an incorrect mask being applied or an invalid memory access.

### Run-Mode Store Program Deletion

When Run-Mode Store was used to delete programs and more than 8 programs existed in the PLC, subsequent Run-Mode Store operations that added programs sometimes resulted in one of the programs being deleted.

## Restrictions and Open Problems

1. When a C block containing floating-point math operations executes in Microcycle mode, and the microcycle base scan is shorter than the PLC sweep time, the C floating-point math functions may detect false errors and log PLC faults. These errors disappear when the microcycle base scan is longer than the PLC sweep time.
2. If an expansion rack powers up while the CPU in the main rack is in the RUN mode, the slot fault contacts will prematurely indicate that the modules in the expansion rack are not faulted before they complete their power up.
3. When there is no logic stored in a CPU module the %Q and %M tables will be cleared when the CPU is placed in RUN mode. In this context, "no logic stored" means that no program had ever been stored or that the clear function on Logicmaster 90 had been used to clear logic and configuration.
4. When the Bit Sequencer sequences from one step to another, the negative transitional contact that corresponds to the original step is not set. The transition contact for the new step is set and remains set until the sequencer sequences to the next step. This operation is identical to the operation of the previous versions of the CPU firmware.
5. If multiple faults exist in a 90-70 Remote Drop and one of them is corrected, a FAULT contact that uses the Remote Drop's module reference will incorrectly indicate that no faults exist at the Remote Drop.
6. An incorrectly formatted COMMREQ (e.g. incorrect task id field) directed to a PCM or CMM module does not result in an error being logged in the PLC fault table. Correctly formatted COMM\_REQs operate normally.
7. The bit sequencer function block clears bits outside the range of the functions length parameter when the reset condition is TRUE. The affected bits lie within the bytes accessed by the function. For example, with length 100 (bits), the four bits at 101, 102, 103, and 104 are cleared by the bitseq function when it is reset. This operation is identical to the operation of the previous versions of the CPU firmware.
8. A large number of COMM\_REQs (typically greater than 8) sent to a given board in the same sweep may cause Module Software fault to be logged in the PLC fault table. The fault group is MOD\_OTHR\_SOFTWR (16t, 10h) and the error code is COMMREQ\_MB\_FULL\_START (2). When this occurs, the "FT" output of the function block will also be set. To prevent this situation, COMM\_REQs issued to a given board should be spread across multiple sweeps so that only a limited number (typically 8 or less) of COMM\_REQs are sent to a given board in each sweep. In addition, the FT output parameter should be checked for errors. If the FT output is set (meaning an error has been detected), the COMM\_REQ could be re-issued by the application logic.
9. When attempting simultaneous loads of logic through multiple Ethernet connections and a serial connection, the loads through the Ethernet connection may fail with a communication timeout.
10. On occasion, the PLC may fail to respond to an SNP Attach message issued through the additional Serial Ports (Port 1 or Port 2). Several retries of the SNP Attach message may be necessary to successfully attach to the PLC via these two ports. Therefore, a user developing their own SNP applications to run on these two ports should design and code for multiple SNP Attach retries.
11. An attempt to read a word value from a 3<sup>rd</sup> party VME module which does not support word wide accesses occurs, and the module responds to a GE Fanuc slot assigned address, the module will generate a System Bus Error fault. Please see the Special Operation Notes for more information on this issue.